

September 17, 2008

Alco Machine Works
6925 - 104 Street
Edmonton, Alberta
T6H 2L5

1105N

Equipment Certification

Rig No.: N/A
Equipment: JR Side Door Casing Elevator
Model: 11 3/4" - 90° - SLX 150 Ton
Serial No.: 80523
Inspection Report No.: H-22357
Engineering File No.: 93233-E
APEGGA Permit to Practice No.: P07208

The above-mentioned elevator required a Level IV inspection (as per Canadian Association of Oilwell Drilling Contractors, R.P. 2.0), applicable repairs, and certification for service.

A magnetic particle (MT) inspection was conducted on September 09, 2008, after the elevator was completely disassembled and sandblasted.

Repair procedures were developed based on the MT inspection report as well as a thorough visual examination performed by qualified personnel with Alco Inc.

Based on the final inspection on September 16, 2008, after load testing, it is our opinion that the elevator is a safe operating unit and may be returned to service within the manufacturer's original rating and specification.

This certification is valid for a period of 500 operating days, as per the recommendations provided by the Canadian Association of Oilwell Drilling Contractors, or until the elevator has been damaged either as a result of operation, transportation or handling.

