



**ALCO INC. HEAD OFFICE**  
6925 - 104 Street, Edmonton, Alberta T6H 2L5  
Office: (780) 435-3502  
Website: www.alcoinc.ca

December 11, 2018  
Edcon Power Tongs & Oilfield  
Box 209  
Lac La Biche, Alberta  
T0A 2C0

### Certificate of Conformance

---

<b>CUSTOMER:</b>	Edcon Power Tongs & Oilfield Services Ltd.
<b>CUSTOMER EQUIPMENT # :</b>	50146 (Edcon S/N 412)
<b>CUSTOMER RIG # :</b>	N/A
<b>EQUIPMENT DESCRIPTION:</b>	RT Side Door Casing Elevator
<b>MODEL AND RATING:      100 Tons</b>	4 1/2" NU SLX-100, 100 Ton (88964-daN)
<b>INSPECTION COMPANY / REPORT #:</b>	Alco / H -N/A
<b>ALCO ENGINEERING FILE # :</b>	61442-2-E
<b>ALCO WORK ORDER # :</b>	61442-2

---

This document specifies that all parts and/or assemblies for the equipment referenced above are sold under the manufacturer's warranty.

The above referenced items are to be used according to the manufacturer's directions and ratings. Alco assumes no responsibility for defective parts or assemblies or any costs associated with their repair due to normal use or misuse.

Manufacture's documentation indicate a load test to 1.5 times this component's rating has been done. Material ductility requirements conform to those specified by the American Petroleum Institute's (API) section 8c.

A CAODC Recommended Practice Level IV inspection is typically required after: 500 operating days.

Brian Kulak, P.Eng  
Sr. Engineer  
Alco Inc.

