



ALCO INC. HEAD OFFICE

6925 - 104 Street, Edmonton, Alberta T6H 2L5

Office: (780) 435-3502

Website: www.alcoinc.ca

April 22, 2024

Edcon Power Tongs & Oilfield Services Ltd.

Box 209

Lac La Biche, Alberta

T0A 2C0

EQUIPMENT CERTIFICATION

CUSTOMER:	Edcon Power Tongs & Oilfield Services Ltd.
CUSTOMER EQUIPMENT # :	N/A <i>700A</i>
CUSTOMER RIG # :	N/A
EQUIPMENT DESCRIPTION:	Alco Elevator Bushing
MODEL AND RATING:	<u>Tons (US)</u> 6 5/8"
INSPECTION COMPANY / REPORT #:	Alco / H -36339
ALCO ENGINEERING FILE # :	94406-E
ALCO WORK ORDER # :	94406


This document certifies that all parts and/or assemblies for the equipment listed above, have undergone a Level IV inspection and repair as per Canadian Association of Oilwell Drilling Contractors (CAODC) R.P. 2.0.

All Engineering, material acceptance, repairs, modifications, dimensional inspections, proof test and non-destructive testing (NDT) were performed, or approved by Alco Inc. qualified personnel adhering to API Q1 (Alco licence #: Q1-2406), where applicable

The equipment may be returned to service at the referenced equipment rating.

This certification is valid for a period of 500 operating days from the date indicated on the Engineer's stamp shown below, or until such time that the equipment has been damaged either as a result of normal use or misuse, transportation or handling.

Brian Kulak, P.Eng
Engineering Manager
Alco Inc.



PERMIT TO PRACTICE	
ALCO INC., GENERAL PARTNER OF THE ALCO LIMITED PARTNERSHIP	
RM SIGNATURE:	<i>B. Kulak</i>
RM APEGA ID #:	30312
DATE:	Apr 22 2024
PERMIT NUMBER: P010702	
The Association of Professional Engineers and Geoscientists of Alberta (APEGA)	



April 2, 2024

Edcon Power Tongs & Oilfield Services Ltd.
 Box 209
 Lac La Biche, Alberta
 T0A 2C0

Certificate of Conformance

CUSTOMER:	Edcon Power Tongs & Oilfield Services Ltd.
CUSTOMER EQUIPMENT # :	231218
CUSTOMER RIG # :	N/A <i>700A</i>
EQUIPMENT DESCRIPTION:	RT Center Latch Casing Elevator
MODEL AND RATING: 150 Tons (US)	7", TA-150, 150 Ton (133446-daN)
INSPECTION COMPANY / REPORT #:	Alco / H-N/A
ALCO ENGINEERING FILE # :	84440-2-E
ALCO WORK ORDER # :	84440-2


This document specifies that all parts and/or assemblies for the equipment referenced above are sold under the manufacturer's warranty.

The above referenced items are to be used according to the manufacturer's directions and ratings. Alco assumes no responsibility for defective parts or assemblies or any costs associated with their repair due to normal use or misuse.

Manufacture's documentation indicate a load test to 1.5 times this component's rating has been done. Material ductility requirements conform to those specified by the American Petroleum Institute's (API) section 8c.

A CAODC Recommended Practice Level IV inspection is typically required after: 500 operating days.

Brian Kulak, P.Eng
 Engineering Manager
 Alco Inc.



PERMIT TO PRACTICE	
ALCO INC., GENERAL PARTNER OF THE ALCO LIMITED PARTNERSHIP	
RM SIGNATURE:	<i>Brian Kulak</i>
RM APEGA ID #:	30312
DATE:	Apr 2 2024
PERMIT NUMBER: P010702	
The Association of Professional Engineers and Geoscientists of Alberta (APEGA)	