

January 12, 2010

Edcon Power Tongs + Oilfield Services Ltd.

Box 209

Lac La Biche, Alberta

T0A 2C0

Equipment Certification

Rig No.: N/A
Equipment: 7" - 90° - 65 Ton
Model: AOT Side Door Casing Elevator
Customer P.O.: N/A
Serial No.: EQ#769
Inspection Report No.: H-24176
Alco Sales/Engineering No.: 789-E
APEGGA Permit to Practice No.: P10702
Alco Shop Work Order # : 33333

The above-mentioned elevator required a Level IV inspection (as per Canadian Association of Oilwell Drilling Contractors, R.P. 2.0), applicable repairs, and certification for service.

A magnetic particle (MT) inspection was conducted on December 17, 2010, after the elevator was completely disassembled and sandblasted.

Repair procedures were developed based on the MT inspection report as well as a thorough visual examination performed by qualified personnel with Alco Inc.

Based on the final inspection on January 12, 2010, after load testing, it is our opinion that the elevator is a safe operating unit and may be returned to service within the manufacturer's original rating and specification.

This certification is valid for a period of 500 operating days, as per the recommendations provided by the Canadian Association of Oilwell Drilling Contractors, or until the elevator has been damaged either as a result of operation, transportation or handling.

