

Red Deer, Alberta

ph.: 519-383-2156

email: protech@pedengineering.com

Issued to:

Edcon Power Tongs and Oilfield Services Ltd. Lac La Biche, Alberta T0A 2C0 August 6, 2009

CERTIFICATION OF OVERHEAD EQUIPMENT

Equipment:	Casing Elevator
Description:	M&W 7" 90 deg. 65 ton
Repair Shop:	Hi Quality Machine & Oilfield
CO No.:	783
Inspection Service:	Tartan NDT Services Ltd.
Job No.:	0330
Field Report No.:	M-3165 & M-3155
Load Test Certification No.:	RS38825-4
Protech Equipment Design File No.:	108153-03

This certification applies to the described equipment. Inspection of this equipment was performed by Tartan NDT Services Ltd. (Mr. G. McLean, CGSB 4901 Level II) using magnetic particle inspection techniques. Furthermore, the equipment was load tested at 1.5 times the rated capacity. Critical dimensions were measured and the unit was visually inspected. No defects or non-conformities were detected or apparent at anytime during these tests and inspections.

This level IV certification is in accordance with the recommended practice of CAODC RP-4.0 and is valid for 500 days or until the equipment is damaged by handling or operation. The equipment shall be operated in strict accordance with CAODC practice including the requirement that it be inspected by a qualified person at commencement of each work shift. In the event the equipment shows wear or damage it must be taken out of service for repair and recertification.

Protech Equipment & Design ONA APEGGA Permit No.: P10692 S eman, P.Eng.

Red Flame Industries



Asset ID : 26295 (Tool# 783)

Report # : NDT17716-TS1044						
Client :	Edcon Power Tongs & Oilfield - Lac La Biche					
Inspection Date :	Oct 23, 2017					
Inspection Location :	Lac La Biche					
Client Ref :	MPI Inspection					

Red Flame Industries Testing Equipment							
Yoke							
Make	Model	Serial#	Calibration	Expires Date			
Magnaflux	Y-1	762	Feb 16, 2017	Feb 16, 2018			

Magnetic Particle Examination Information and Results

Material Type: Carbon Steel Temperature: 0° to 20°C Surface Preparation: Painted Acceptance Criteria: Red Flame Engineering Acceptance Technique Used: AC Dry Powder - Continuous Procedure: MT-1 Rev. 8.3 In accordance with codes: ASME V Article 7, ASME B30.20

Branch: Lac La Biche

Client WO : Client PO : Jay

Results Magnetic Particle Examination Conducted On - Casing Elevator - 7.000" - 177.800MM 65 Ton - 26295 (Tool# 783)

Visible Dry Particle Examination Conducted With AC Powered Yoke.

Multidirectional Field Achieved By Repositioning Yoke At Right Angles In Each Area Examined. Powder Applied With Hand Blower. Batch Number 16F104 Powder Removal By Light Exhalation. Minimum White Light At Examination Surface: 1000 Lux. Particle Size 2-6 im. Particle Color: YELLOW.

Examination Conducted On 7" Elevator; All Accessible Surfaces, Transition Areas And Lift Points On Fully Assembled Painted Elevator As Requested.

Results: No Relevant Indications Were Detected At The Time Of Examination.

See Photo.

Red Flame Industries Personnel Information

Technician: Tom Schulz SNT-MT2 SNT-UT2 SNT-PT2 CGSB-MT2 - 17965 Assistant:

Signature:

Red Flame Industries

Red Flame Industries





783.jpg Report Attachments

Red Flame Industries

6736-71 Street, Red Deer Alberta, Canada T4P 3Y7 Phone: (403) 343-2012 Toll Free: (888) 846-8827 Page 2 of 2